	Bear	Receive Planning Div 06/30/20 Verton E G O N	r <mark>ision</mark> 21	illikan Way PC	EXHIBIT 3.17 Public Works Department D Box 4755 Beaverton, OR 97076 p: 503-526-2269 www.BeavertonOregon.gov					
	Water Sei	rvice Provider	Letter (SPL)						
	SITE INFORMA Tax Map(s): Size: Address: Nearest cross-st SW 1397TH ALATTK	Lot Num CALES Lot Num CALES LOT NAME: HER LOT NAME: HER LOT NAME: HER	nber(s): 3300 wky e): JV	APPLICANT: Contact: Company: Address: Phone: Email: <u>OWNER(S)</u> : Contact: Company: Address: Phone: Email: <u>VOLKSUNCE</u>	TROITDALE OR 97060 903-668-3737 608 - 3737 600 Firecoldesign. com MIKE HERZOG HEZZOG PROPERTIES U.C 4275 SU 139TH WAY BEAVERION, OR 97005 903-644-9121 MIKE. Ner ZOG ChevZOG Meier. CO 203-644-9121 MIKE. Ner ZOG ChevZOG Meier. CO 201 VOLVO NEW SERVICE BULG	om				
	TESIG	N REVIEW AUTO DEALERSN				-				
	RESIDENTIAL:		INDUSTRIAL/COM	MERCIAL:	CONDITIONAL USE:					
	Single Fam. N									
Average [of Units: Daily Demand (ga									
	FIRE FLOW REC	QUIRED: (gpm): <u>450</u>		IRRIGATION F ± 50,000	ELOW REQUIRED: (gpm): 30) gal 1 month in peak season					
	***			APPLICANT: Contact: PLAKE DAVIS Company: FIRMOD DESKINGROP Address: 399 E HISTORIC COMMENT A RIVER HUNC TROUTDALE OR 97060 Phone: 933-668-3737 Email: bd@ Firmod design.com OWNER(S): Contact: MIKE HER 200 Company: HR2209 PROPERTIES LLQ Address: 4275 SW i39TH WAY DEAVERTON, OR 9705 Phone: 203-644 - 9121 Email: MIKE HER 209 Meres Com ELER VOLVSWATENT VOLVO ARD SERVICE BUILDING Review, Land Division, Conditional Use, etc.): MR PROPOSED USE: AUTO VCALERSHIP & REPAKE ALCOMMERCIAL: CONDITIONAL USE: (IMMERCIAL: CONDITIONAL USE: (
	***Both agency signatures required									

TVWD ADEQUATE INADEQUATE SERVICE LEVEL TO SERVE THE PROPOSED PROJECT. Describe why service level is inadequate and needed improvements or modification required to provide adequate services. (Use additional sheets to explain if necessary)

SIGN	IATURE:	TITLE:	DATE:							
is inadequate a if necessary)	COB ADEQUATE INADEQUATE SERVICE LEVEL TO SERVE THE PROPOSED PROJECT. Describe why service level is inadequate and needed improvements or modification required to provide adequate services. (Use additional sheets to explain if necessary) Service can be provided from SW 139th Way. Bldg/Plumbing Dept. will determine meter size required based on fixture count per code. Current Water SDC charges can be found @ https://www.beavertonoregon.gov/345/Development-Charges									
signature: <u>Brion Barnett</u> Stream Courses and Courses										

Form Date: 02-17-2019