

Kim-Hien Nguyen
kimhiensr@gmail.com

24 March 2023

Danelle Isenhart
danelle@isenhartconsulting.com

Re: Infiltration testing at 4975 SW 139th Avenue, Beaverton, OR

Dear Ms. Nguyen,

Field Investigation:

Rapid Soil Solutions (RSS) has performed one (1) infiltration test. Figure 1 below shows the project site location. Soils found on site match those in by DOGMI. RSS found very stiff fine-grained soils




Figure 1

Infiltration Testing:

RSS attempted two tests in the backyard of the above house and hit water at depth at 3ft. RSS does not recommend onsite infiltration due to shallow ground water.

The analysis, conclusions and recommendations contained in this report are based on site conditions as they existed at the time of explorations. Any questions regarding this report please contact me at the below number or email.

Sincerely,



EXPIRES:
12/31/2024

Mia Mahedy, PE GE.